


# GUNOLD®



## Use and care of **KK 2000** spray cans

1. Never use KK 2000 close to your embroidery machine. The spray adhesive may permanently damage important parts of your machine.

Apply KK 2000 at a separate work table.

2. Place the fabric to be sprayed flat on your work table.
3. Hold can approx. 20-30 cm away from surface to be sprayed, preferably in the most upright position.
4. For proper dispersion of the glue, press nozzle as far down as possible.
5. Once spray can nearly runs empty, it may be necessary to rotate spray nozzle to finish the contents of the can.
6. Should spray nozzle clog up, turn the can upside down and spray. If this does not unclog the nozzle, exchange it with a nozzle of another can. Tip: Save nozzles from empty cans.

Spray nozzles can be cleaned by soaking them in turpentine for a few minutes.

**Important:** Never insert needles or similar objects into the nozzle as this may deform the spray channel, causing changes of the misting pattern.